.0	m	a
Æ.	w	Ph.
and a	-	v

	 777.00
Register No.:	

April 2019

Time - Three hours (Maximum Marks: 75)

- [N.B: (1) Q.No. 8 in PART A and Q.No. 16 in PART B are compulsory.

 Answer any FOUR questions from the remaining in each PART A and PART B
 - (2) Answer division (a) or division (b) of each question in PART C.
 - (3) Each question carries 2 marks in PART A, 3 marks in Part B and 10 marks in PART - C.]

PART - A

- 1. Define measurement.
- 2. What is continuous method of data presentation?
- Name any two displacement transducer.
- Define torque.
- 5. State any two units for pressure.
- Define mean velocity.
- 7. Define flow rate.
- 8. Name any two temperature transducer.

PART - B

- Define median.
- 10. State different methods of measurement.
- 11. What is fluid cell?
- 12. Define force and state its unit.
- 13. What is strain gauge? State its types.
- Define mean velocity.
- 15. What is orifice? State its type.
- 16. Draw the continuous diagram.

PART - C

17. (a) Define mean, mode and median.

(Or)

- (b) Define accuracy, reliability, sensitivity, reproducibility and calibration.
- 18. (a) Briefly explain about histogram.

(Or)

- (b) Explain about analysis of experimental data.
- (a) With neat sketch, explain electrical method of displacement measurement.

(Or)

- (b) Explain measurement of torque with neat sketch.
- (a) With neat sketch, explain U-tube manameter for pressure measurement.

(Or)

- (b) With neat sketch, explain thermocouple.
- 21. (a) Explain venturi type flow meter.

(Or)

(b) Explain Rota meter type flow measurement.