## B.E/B.TECH, M.E/M.TECH, MBA, MCA, POLYTECHNIC & SCHOOL

Notes Syllabus Question Papers Results and Many more... Available @ www.binils.com

Reg. No. :	
Discuss about the following tool manuals in their composition,	(8) II
Question Paper Code: 50873	
B.E./B.Tech. DEGREE EXAMINATIONS, APRIL/MAY 2023.	
Fourth Semester	
Mechanical Engineering	
ME 8451 — MANUFACTURING TECHNOLOGY – II	
(Common to Industrial Engineering/ Industrial Engineering and Manage Mechanical Engineering (Sandwich)/Mechanical and Automation Engine	
(Regulations 2017)	
Time: Three hours Maximum: 10	00 marks
Answer ALL questions.	
PART A — $(10 \times 2 = 20 \text{ marks})$	
1. Define rake angle.	
2. What is oblique cutting?	
3. Write any four operations that can be performed on lathe.	
4. What is the use of mandrel?	
5. Differentiate between vertical shaper and slotter.	
6. Define up-milling and down milling.	
7. List the abrasives used in the manufacture of abrasive wheel.	
8. Define honing.	
Explain about micromachinung.	
9. Classify NC machines.	
10. Write the functions of codes M00 and M01.	

## B.E/B.TECH, M.E/M.TECH, MBA, MCA, POLYTECHNIC & SCHOOL

Notes Syllabus Question Papers Results and Many more...

Available @ www.binils.com

			PART B — $(5 \times 13 = 65 \text{ marks})$	
			Reg. No.	
	11.	(a)	Discuss about the following tool materials in terms of their compositions and applications:	tion,
			(i) Carbon steels	(4)
			(ii) HSS	(3)
			(iii) Cemented carbides and	(3)
			(iv) Ceramics.	(3)
			Or	
		(b)	Classify and Elaborate tool wear.	
	12.	(a)	Differentiate between capstan and turret lathe.	
			parield has paressayed Livis Or parison a largement of more more	
		(b)	Discuss the following lathe operations in brief:	
			(i) facing	(4)
			(ii) knurling and	(5)
			(iii) drilling.	(4)
	13.	(a)	Calculate the time required for taking a complete cut on a $\mu$ 600 $\times$ 800 mm if the cutting speed is 10 m/min. The ratio of cutting to return stroke is 4:1 feed is 2 mm. Take the clearance at each en 25 mm.	time
			Or Sportfus smilds at 16 dW.	
		(b)	A M.S. bar of $400\times500$ mm is to be machined using a shaper. Find time taken to complete one cut at a cutting speed of 12 m/min. The of return time to cutting time is 2:3 and the feed is 1.25 mm. Take clearance at each end as 75 mm.	ratio
	14.	(a)	Discuss about:	
			(i) traverse grinding the manufacture of the state of the	(5)
			(ii) plunge cut grinding and	(4)
			(iii) full depth grinding in brief.	(4)
			leady eviscads to out $\mathbf{Or}$ named in the wheel of abrasive wheel	
		(b)	Explain about centreless grinding with neat sketches.	
	15.	(a)	Explain about micromachining.	
			Or sendem OV Alexa D	
		(b)	Explain about Numerical machine tools.	
				0873
			2	,010

## B.E/B.TECH, M.E/M.TECH, MBA, MCA, POLYTECHNIC & SCHOOL

Notes
Syllabus
Question Papers
Results and Many more...

Available @ www.binils.com

## PART C — $(1 \times 15 = 15 \text{ marks})$ 16. (a) In an orthogonal cutting of 40 mm dia steel tube, the data given are: rake angle = 35°, cutting speed 20 m/min, feed = 0.1 mm/rev, cutting force = 2000N and feed force = 800N. Continuous chip length in one length is 50 mm. Calculate coefficient of friction, shear angle, chip velocity and chip thickness at tool force. A through hole 38 mm in diameter is to be finished to 42 mm using a drilling machine. The total thickness of the work piece is 50 mm. Calculate the depth of cut and machining time. Take cutting speed as 0.32 m/s and feed as 0.6 mm /revolution.

3

50873